

# Service Letter



## 1. General

(a) No.:	SL 3
(b) Revision / Date	A / March 2017
(c) Title:	Notification of 'Rotax' Alert Service Bulletin
(d) Description:	Possible malfunction of carburettor float on Rotax 582UL engine
(e) Applicability:	Cameron DP-60, DP-70, DP-80, DP-90 and 'AS' series hot air airships.
(f) Effectivity:	All CNs using Rotax 582UL engines

**Note:** Applicability= All types and variants to which the advice can be applied.  
Effectivity= Actual CN or group of CN's to which the advice applies.

## 2. Accomplishment Instructions

Comply with Rotax alert service bulletin ASB-912-069ULR1/ ASB-914-051ULR1/ ASB-2ST-003R1 which call up ASB-912-069R1/ ASB-914-051R1. See also Rotax service instruction SI-912-021/ SI-914-023/ SI-2ST-009.

**3. Materials** Float, gasket, 'o' ring.

**4. Other Publications Affected** none

**5. Remarks** none

Compiled by: \_\_\_\_\_ Notes:

*Tom Boxall*

Date: 23 Mar 2017 Name: D.C. Boxall

## 6. Design Organisation Approval

### Approval Statement

I hereby confirm that these instructions are in compliance with all the applicable airworthiness requirements. The technical content of this document is approved under the authority of DOA nr EASA.21J.140

Signed, for and on behalf of Cameron Balloons Ltd.

*B.E. Bowet*

Head of Design

Date: 23-03-2017 Name:

