

CAMERON BALLOONS LTD (THUNDER & COLT)

SERVICE BULLETIN: SB5

Subject: **Super Shadow / Single Super Shadow / Stealth Burners**

Title: **A) Replacement of Main Blast Valve Stems.
B) Blast Valve free Movement check.**

Parts affected: **Super Shadow / Single Super Shadow / Stealth Burners
from March 1997 (see Appendix I).**

Reason for Modification/
Inspection. **A) Incorrect surface finish on blast valve stems.
B) Lack of Free Movement in the blast valve.**

Modification Classification: **Highly Recommended**

Compliance: **A) Replacement in accordance with CBL/TN/JD/1514.
Remedial action must be taken before the next annual inspection.
B) Inspection in accordance with CBL/TN/JD/1573**

Possible Consequence of Non-Compliance: **Blast Valve could stick open requiring remedial action in accordance with Cameron Balloons Flight Manual Issue 7, Section 3 - Emergency Procedures Para. 3.8**

Accomplishment Instructions. **CBL/TN/JD/1514 Issue C.**

If in doubt please contact the factory.

**Cameron Balloons Ltd /Thunder and Colt
St John's Street
Bedminster
Bristol
BS3 4NH**

**Tel +44 (0)117 9637216
Fax +44 (0)117 9661168**